
T50 – LUMO
LED TORCH
OWNER'S MANUAL

Thank you very much for purchasing IST LUMO dive torch. The T50 is super compact but the amount of illumination it produces is unrivalled by anything similar in size on the market today. The ultra bright LED is housed in a sturdy, marine-grade aluminum housing. To get the most out of this torch, please read through the manual completely before using this product. Should you have any question, please do not hesitate to contact your nearest IST authorized dealer or distributor for assistance.

USING THE TORCH:
Battery Installation



POWER INDICATOR:
The power indicator turns red when the battery holds less than 30% capacity



- Double click the power switch button to turn the power on.
- LUMO will be set in high-power mode when turned on; press the power switch button to change the mode in the sequence of low-power—SOS—OFF.

BEFORE EACH DIVE:
- Make sure the battery is fully charged.
- Inspect all o-rings are in clean, good condition. If in doubt, do not use the torch until the o-rings are cleaned or replaced. In any case they should have a thin film of silicone grease on them for protection.
- Close the battery compartment cap and turn the torch on o see if it is functioning properly.

BEFORE EACH DIVE:
- Turn the torch off (if possible) and thoroughly clean the exterior with fresh water.

Although the lithium-ion battery has no memory effect, deep-discharge (e.g. when power is completely drained) is highly detrimental and recharging should take place as soon as possible to minimize damages.

STORAGE:
- It is very important to store your torch (especially the battery) in a cool, shaded and dry place. Do not expose them to extreme conditions such as direct sunlight, heat, ozone etc. In fact, it is highly recommended to keep the battery in the coolest storage place that is conveniently possible as the higher the temperature, the quicker the lithium-ion battery will degrade and lose its capacity.
- Store the torch and battery separately.